



TROUBLESHOOTING

Description	Troubleshooting	Repair Kit No.
Cartridge Kit	<ul style="list-style-type: none"> Water leaks at valve stem and/or bonnet. Water leaks at valve shut-off. Water temperature changes during shower. 	220-060
Checkstop Replacement Kit	<ul style="list-style-type: none"> Checkstop leaks or will not shut-off completely. 	900-050

CALIFORNIA PROPOSITION 65 WARNING
WARNING: This product contains chemicals known to the State of California to cause cancer and birth defects or other reproductive harm. (Installer: California law requires that this warning be given to the consumer.)
 For more information: www.wattsind.com/prop65

POWERS
A WATTS INDUSTRIES CO.

© June 2003 Powers, a Watts Industries Co.
 USA Phone: 800.669.5430 • www.powerscontrols.com
 Canadian office: Phone: 888.208.8927